

DN8000k10PCI Errata

Symptom/Problem:

The following functions do not work:

- (1) Read back of FPGA temperatures over PCI
- (2) Setting ACLK/BCLK/DCLK over PCI
- (3) BAR0 transactions to offset 0x258 and 0x260

Solution:

Update the ConfigFPGA prom file.

Action:

Contact The Dini Group at (858)454-3419 or email support@dinigroup.com to get the latest ConfigFPGA prom file.